

RMS Queen Elizabeth 2 (QE2) (1969): Sources

(Upper Clyde Shipbuilders Ltd, Clydebank, Yard No. 736)

How to use this list of sources

These are the resources we have available for researching this vessel. Enquiries should be directed to the Duty Archivist - contact details are at the end of this list.

Cunard Letter Books		
GUAS Ref: UCS 1/16/32		Aug 1965-
		Jun 1966
GUAS Ref: UCS 1/16/33		Jun 1966-
CLIAS Def: LICS 1/16/24		Feb 1967
GUAS Ref: UCS 1/16/34		Feb 1967- Nov 1967
GUAS Ref: UCS 1/16/35		Nov 1967-
		Sep 1968
Enquiries Tenders and Ca	entresta Files	
Enquiries, Tenders and Co GUAS Ref: UCS 1/21/240		1064
	Building Agreement and Financial Agreement	1964
Estimating Books		
GUAS Ref: UCS 1/73/17	Steel Estimates	
GUAS Ref: UCS 1/73/18	Work Book for Steel Estimates	
GUAS Ref: UCS 1/73/19	Wood and Outfit Estimates	
Files		
GUAS Ref: UCS 1/107/427	Contract Correspondence; Progress	1967-68
	reviews, effects of merger on shipyards etc	
GUAS Ref: UCS 1/107/428	Publicity concerning construction etc; launch	1966
	arrangements	
GUAS Ref: UCS 1/107/436	Tender, agreement, notes of meetings,	1964-68
	contract correspondence	4004.00
GUAS Ref: UCS 1/107/437	Tender, agreement, notes of meetings, contract correspondence	1964-68
GUAS Ref: UCS 1/107/438	Tender, agreement, notes of meetings, contract	1964-68
66A6 Kel. 666 1/10//436	correspondence	1904-00
GUAS Ref: UCS 1/107/439	General Correspondence; liquidated damages	1964-68
	and notes of meetings	
GUAS Ref: UCS 1/107/440	Miscellaneous notes and correspondence	1964-68
GUAS Ref: UCS 1/107/441	Miscellaneous notes and correspondence	1967
GUAS Ref: UCS 1/107/442	Minutes of Progress meetings	1967-68
GUAS Ref: UCS 1/107/443	Minutes of meetings with Cunard	1964-67
GUAS Ref: UCS 1/107/444	Agreements, certificates, notes of meetings	1967-69
GUAS Ref: UCS 1/107/445	Insurance, subcontractors, press releases, fire	1967-69
	and security arrangements, correspondence	1005 07
GUAS Ref: UCS 1/107/446	Financial papers, cost estimates, progress etc	1965-67
GUAS Ref: UCS 1/107/447 GUAS Ref: UCS 1/107/448	Board papers and costing reports	1967-68
GUAS Ref: UCS 1/10//448 GUAS Ref: UCS 1/107/449	Trade progress reports	1967-68 1967-69
GUAS Ref: UCS 1/107/449 GUAS Ref: UCS 1/107/450	Miscellaneous costing returns, certificates etc Price revisions, correspondence	1967-69
GUAS Ref: UCS 1/107/450	Price variation conditions	1965-68
GUAS Ref: UCS 1/107/452	Escalation returns to Cunard	1965-68
		1000 00

Files (continued)

GUAS Ref: UCS 1/107/453Escalation, General File1965-68GUAS Ref: UCS 1/107/454Escalation, General File1965-68GUAS Ref: UCS 1/107/455Summaries of final cost1967-68GUAS Ref: UCS 1/107/456Costing statements and correspondence, certificates, payments at delivery, final price, catims etc1968-69GUAS Ref: UCS 1/107/457Reports on Joinery Progress1968GUAS Ref: UCS 1/107/458Reports on Joinery Progress1968-69GUAS Ref: UCS 1/107/450Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/450Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Braznol Lindey to Minister of1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory1970Services Department of Lloyds Register of Shipping <b< th=""><th>Files (continued)</th><th></th><th></th></b<>	Files (continued)		
GUAS Ref: UCS 1/107/455Summaries of final cost1966-68GUAS Ref: UCS 1/107/456Forecasts and final costs1967-763GUAS Ref: UCS 1/107/457Costing statements and correspondence, certificates, payments at delivery, final price, claims etc1968-71GUAS Ref: UCS 1/107/458Reports on Joinery Progress1968GUAS Ref: UCS 1/107/459General Defects1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/467Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969-70GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1969GUAS Ref: UCS 1/107/467Test Report by Associated Electrical Industries Ltd on 55 MW Tu	GUAS Ref: UCS 1/107/453	Escalation, General File	1965-68
GUAS Ref: UCS 1/107/457 Forecasts and final costs 1967-68 GUAS Ref: UCS 1/107/457 Costing statements and correspondence, calims etc 1968-71 GUAS Ref: UCS 1/107/458 Reports on Joinery Progress 1968 GUAS Ref: UCS 1/107/459 General Defects 1968-69 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1968-69 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1969 GUAS Ref: UCS 1/107/462 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/463 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/463 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/464 Turbine Vibration and Blade Failures, Shaft 1969-70 GUAS Ref: UCS 1/107/465 Turbine Vibration and Blade Failures, Shaft 1969-70 GUAS Ref: UCS 1/107/466 Report by Research and Technical Advisory 1969	GUAS Ref: UCS 1/107/454	Escalation, General File	1965-69
GUAS Ref: UCS 1/107/457 Forecasts and final costs 1967-68 GUAS Ref: UCS 1/107/457 Costing statements and correspondence, calims etc 1968-71 GUAS Ref: UCS 1/107/458 Reports on Joinery Progress 1968 GUAS Ref: UCS 1/107/459 General Defects 1968-69 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1968-69 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1969 GUAS Ref: UCS 1/107/462 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/463 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/463 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/464 Turbine Vibration and Blade Failures, Shaft 1969-70 GUAS Ref: UCS 1/107/465 Turbine Vibration and Blade Failures, Shaft 1969-70 GUAS Ref: UCS 1/107/466 Report by Research and Technical Advisory 1969	GUAS Ref: UCS 1/107/455	Summaries of final cost	1966-68
GUAS Ref: UCS 1/107/457 Costing statements and correspondence, claims etc 1969-71 GUAS Ref: UCS 1/107/458 Reports on Joinery Progress 1968 GUAS Ref: UCS 1/107/459 General Defects 1968-69 GUAS Ref: UCS 1/107/460 Turbine Vibration and Blade Failures, Shaft 1968-69 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/461 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/463 Turbine Vibration and Blade Failures, Shaft 1969-70 Wear etc; memoranda, reports, notes of meetings, correspondence and technical data 1969-70 GUAS Ref: UCS 1/107/464 Turbine Vibration and Blade Failures, Shaft 1969-70 GUAS Ref: UCS 1/107/467 Report by Research and Technical Advisory 1969-70 GUAS Ref: UCS 1/107/467 Report by Research and Technical Advisory 19		Forecasts and final costs	
certificates, payments at delivery, final price, claims etcGUAS Ref: UCS 1/107/458Reports on Joinery Progress1968GUAS Ref: UCS 1/107/460Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Research and Technical Advisory1970Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1969GUAS Ref: UCS 1/107/46			
Claims etcReports on Joinery Progress1968GUAS Ref: UCS 1/107/450General Defects1968-69GUAS Ref: UCS 1/107/460Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/470Report by Re			1000 1 1
GUAS Ref: UCS 1/107/458Reports on Joinery Progress1968GUAS Ref: UCS 1/107/450General Defects1968-69GUAS Ref: UCS 1/107/460Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc: memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc: memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc: memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc: memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70Wear etc: memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/467Report by Sir Arnold Lindley to Minister of 19691969-70GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory1970Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1969GUAS Ref: UCS 1/107/468Report by Associated E			
GUAS Ref: UCS 1/107/459General Defects1968-69GUAS Ref: UCS 1/107/460Turbine Vibration and Blade Failures, Shaft1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of Namp Leontaining Typical Cracks) </td <td>CLIAS Dof: UCS 1/107/459</td> <td></td> <td>1069</td>	CLIAS Dof: UCS 1/107/459		1069
GUAS Ref: UCS 1/107/460Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1968-69GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1970GUAS Ref: UCS 1/107/468Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyo			
Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft torrespondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft turbine Vibration and Turbine Vibration turbine Vibratine Vibration and Blade Failures, Vibrine Vi			
GUAS Ref: UCS 1/107/461correspondence and technical data1969Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Bla	GUAS Ref: UCS 1/107/460		1968-69
GUAS Ref: UCS 1/107/461Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Turbine V			
Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1970GUAS Ref: UCS 1/107/468Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out		•	
correspondence and technical data1969-70GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of cont	GUAS Ref: UCS 1/107/461		1969
GUAS Ref: UCS 1/107/462Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Report by Sir Arnold Lindley to Minister of Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stem Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/463Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1969GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cuna		correspondence and technical data	
GUAS Ref: UCS 1/107/463correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/470Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/462	Turbine Vibration and Blade Failures, Shaft	1969-70
GUAS Ref: UCS 1/107/463Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/470Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972		Wear etc; memoranda, reports, notes of meetings,	
Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972		correspondence and technical data	
GUAS Ref: UCS 1/107/464correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/463	Turbine Vibration and Blade Failures, Shaft	1969-70
GUAS Ref: UCS 1/107/464Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/467Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972		Wear etc; memoranda, reports, notes of meetings,	
Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972		correspondence and technical data	
GUAS Ref: UCS 1/107/465correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/464	Turbine Vibration and Blade Failures, Shaft	1969-70
GUAS Ref: UCS 1/107/465correspondence and technical data1969-70GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/465Turbine Vibration and Blade Failures, Shaft Wear etc; memoranda, reports, notes of meetings, correspondence and technical data1969-70GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
Wear etc; memoranda, reports, notes of meetings, correspondence and technical dataGUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine RepairsGUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern BushGUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft Liner (Examination of Sample containing Typical Cracks)GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton	GUAS Ref: UCS 1/107/465	•	1969-70
correspondence and technical dataGUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine RepairsGUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern BushGUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton			
GUAS Ref: UCS 1/107/466Report by Sir Arnold Lindley to Minister of Technology on High Pressure Turbine Repairs1969GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
Technology on High Pressure Turbine RepairsGUAS Ref: UCS 1/107/467Report by Research and Technical Advisory1970Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/466	•	1969
GUAS Ref: UCS 1/107/467Report by Research and Technical Advisory Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			1505
Services Department of Investigation to Determine Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref. LICS 1/107/467		1070
Cause of Excessive Weardown Recorded on Port After Stern Bush1970GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	00A3 Kel. 003 1/10//40/		1370
GUAS Ref: UCS 1/107/468After Stern Bush Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/468Report by Research and Technical Advisory Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)1970GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1972GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
Services Department of Lloyds Register of Shipping of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract 1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract 1972			4070
of Failure of Port Tailshaft, Tailshaft Liner (Examination of Sample containing Typical Cracks)GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton	GUAS Ref: UCS 1/107/468		1970
GUAS Ref: UCS 1/107/469(Examination of Sample containing Typical Cracks) Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/469Test Report by Associated Electrical Industries Ltd on 55 MW Turbine GeneratorGUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/470on 55 MW Turbine Generator1969GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972			
GUAS Ref: UCS 1/107/470Appendices to Possible Claims in connection with Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)1969GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/469	· · ·	
GUAS Ref: UCS 1/107/471Construction of New Cunard Passenger Ship (Shaw and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton			
GUAS Ref: UCS 1/107/471and Hatton, Quantity Surveyors and Consultants)GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972	GUAS Ref: UCS 1/107/470	Appendices to Possible Claims in connection with	1969
GUAS Ref: UCS 1/107/471Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972GUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton1972		Construction of New Cunard Passenger Ship (Shaw	
GUAS Ref: UCS 1/107/472between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton		and Hatton, Quantity Surveyors and Consultants)	
GUAS Ref: UCS 1/107/472and Cunard Line Ltd, by Shaw and HattonGUAS Ref: UCS 1/107/472Report on Contractual Claims arising out of contractbetween Upper Clyde Shipbuilders (in liquidation)and Cunard Line Ltd, by Shaw and Hatton	GUAS Ref: UCS 1/107/471	Report on Contractual Claims arising out of contract	1972
GUAS Ref: UCS 1/107/472 Report on Contractual Claims arising out of contract 1972 between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton		between Upper Clyde Shipbuilders (in liquidation)	
GUAS Ref: UCS 1/107/472 Report on Contractual Claims arising out of contract 1972 between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton			
between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton	GUAS Ref: UCS 1/107/472	-	1972
and Cunard Line Ltd, by Shaw and Hatton			
·			
		-	

Files (continued)		
GUAS Ref: UCS 1/107/473	Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton Appendices: Vol B 1972	1972
GUAS Ref: UCS 1/107/474	Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton Appendices: Vol C 1972	1972
GUAS Ref: UCS 1/107/475	Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton Appendices: Vol D 1972	1972
GUAS Ref: UCS 1/107/476	Report on Contractual Claims arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Ltd, by Shaw and Hatton Appendices: Vol E 1972	1972
GUAS Ref: UCS 1/107/477	Preliminary Statement of Claim arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line	1973
GUAS Ref: UCS 1/107/478	Preliminary Statement of Claim arising out of contract between Upper Clyde Shipbuilders (in liquidation) and Cunard Line Appendices	1973
GUAS Ref: UCS 1/107/479 GUAS Ref: UCS 1/107/480	List of Sub-Contractors Copy Agreement between John Brown & Co (Clydebank) Ltd and Finance Corporation for Industry Ltd relating to the provision of a guarantee	1967 1964
GUAS Ref: UCS 1/107/481	Adjustment of claim on policies on building risks: damage to Turbines	1975
GUAS Ref: UCS 1/107/482	Report by Serck Radiators on condition of turbo generator oil coolers	1969
GUAS Ref: UCS 1/107/483	Claim and Counter-claim litigation: Case for opinion of counsel; opinion, notes etc	1966-74
GUAS Ref: UCS 1/107/484	Notes on progress, trials, delivery dates and action concerning turbine failures	1966-69
GUAS Ref: UCS 1/107/485	Chairman's correspondence and notes: delivery date, turbine problems, labour relations etc	1968-70
GUAS Ref: UCS 1/107/486	Re-engineering project: notes, reports, memoranda and ships particulars Compiled by Scott-Lithgow, Port Glasgow	1984-85
GUAS Ref: UCS 1/107/487	Re-engineering project: Correspondence and plans from MAN - B & W Diesel 1985; Re-engineering project: Draft Specification for replacing steam turbine machinery with diesel electric propulsion machinery	1985
GUAS Ref: UCS 1/107/488	Re-engineering project: Draft Specification for replacing steam turbine machinery with diesel electric propulsion machinery	1985
GUAS Ref: UCS 1/107/489	Re-engineering project: Report No 898 by British Shipbuilders "Main and Generator Waste Heat Recovery for QE2 Conversion"	1984

Files (continued)

GUAS Ref: UCS 1/107/490	Re-engineering project: Report No 901 by British Shipbuilders "Analysis of Electrical Power Demand for QE2"	1984
GUAS Ref: UCS 1/107/491	Re-engineering project: Report No 905 by British Shipbuilders "QE2 Fuel Consumption Analysis"	1984
GUAS Ref: UCS 1/107/492	Re-engineering project: Report No 406 by British Shipbuilders "QE2 Speed/Power Trial"	1984
Historical Notes		
GUAS Ref: UCS 1/106/4	Descriptions of ships built	
Launch Arrangements		
GUAS Ref: UCS 1/113/32	Launch arrangements and 2 plans	
Particular Books		
GUAS Ref: UCS 1/ 93/50	Speed Trials Record Book	
Photographs		
GUAS Ref: UCS 1/116/204	Photograph Album (124 prints)	
Plans		
GUAS Ref: UCS 1/110/736	Plan List	
Specification Books		
GUAS Ref: UCS 1/91/142	Hull	
GUAS Ref: UCS 1/91/143	Machinery and Boilers	
GUAS Ref: UCS 1/91/144	Interior Decorations and Furnishings	
GUAS Ref: UCS 1/91/145	Cabins, Public Rooms, Stairways and Entrances (Decorative Contracts)	

University of Glasgow Archive Services. Copyright reserved. Version 2, March 2007

Page 4 of 4